

C 5040 CalWin



PC control and evaluation software for all IKA® calorimeters (C 200, C 2000, C 5000, C 7000, C 4000).
 requires a PC running any of the following operating systems: Windows 95 / 98 / ME / NT / 2000 or XP, and at least one free serial interface and 50 MB of available disk space.

- Control, monitor and view working procedures
- Print and save measurement protocols
- Identify and record samples
- Administration of sample racks C 5020
- Flexible administration and evaluation of calibrations
- Flexible administration and grouping of measurements
- Printing and saving calibration and result protocols suitable for certification
- Library functions
- Data transfer through COM to EXCEL and ACCESS
- Preprocessed work sheets for EXCEL (configurable by the user)

consisting of:
 C 5040 CalWin
 C 5041.10 connecting cable

Technical Data			
Windows 95 [-]	yes	Windows 98 [-]	yes
Windows ME [-]	yes	Windows NT4 [-]	yes
Windows 2000 [-]	yes	Windows XP [-]	yes