

## C 5041 CalWin plus



PC control and evaluation software for all IKA® calorimeters

(C 200, C 2000, C 5000, C 7000, C 4000).

requires a PC running any of the following operating systems:

Windows 95 / 98 / ME / NT / 2000 or XP, and at least one free serial interface and 50 MB of available disk space.

- ¿ Control, monitor and view working procedures
- ¿ Print and save measurement protocols
- ¿ Identify and record samples
- ¿ Administration of sample racks
- ¿ Flexible administration and evaluation of calibrations
- ¿ Flexible administration and grouping of measurements
- ¿ Printing and saving calibration and result protocols suitable for certification
- ¿ Library functions
- ¿ Data transfer through COM to EXCEL and ACCESS
- ¿ Preprocessed work sheets for EXCEL (configurable by the user)

to control up to 8 calorimeters of the same or different type consisting of:

C 5040 Calwin,

C 5041.10 connecting cable

PCI 8.2 PC Plug-in card, Interface box (8x)

for the connection of more calorimeters s.a. C 200 / C 2000 / C 5000 / C 7000 please order the connecting cable C 5041.10

connecting cable for the C 4000 :

cod. Nr. 2349600

Technical Data			
Windows 95 [-]	yes	Windows 98 [-]	yes
Windows ME [-]	yes	Windows NT4 [-]	yes
Windows 2000 [-]	yes	Windows XP [-]	yes